




VELUX®

PML














**PAGES
4-18**






**PAGES
20-34**




















6






7









8






9







12






13




14













2





3







4







5






6






7












8



9









B04
C01•C02•C04•C06
F04•F06•F08
M04•M06•M08•M10•M12
P25•P04•P06•P08•P10
S01•S06•S08•S10
U04•U08•U10
X99

064
101•102•104
204•206
325•304•306
308•310•312
425•404•406•408•410
601•606•608•610
804•808•810
1•2•3•4•5•6•7•8•9
10•11•13•14•31•999





VELUX®

| | | | |
|------------|---|------------|---|
| AR: | VELUX Argentina S.A. +54 3488 639944 / 45 / 46 | IE: | VELUX Company Ltd. 01 848 8775 |
| AT: | VELUX Österreich GmbH 02245/32 3 50 | IT: | VELUX Italia s.p.a. 045/6173666 |
| AU: | VELUX Australia Pty. Ltd. 1300 859 856 | JP: | VELUX-Japan Ltd. 0570-00-8145 |
| BA: | VELUX Bosna i Hercegovina d.o.o. 033/626 493, 626 494 | LT: | VELUX Lietuva, UAB (85) 270 91 01 |
| BE: | VELUX Belgium (010) 42.09.09 | LV: | VELUX Latvia SIA 67 27 77 33 |
| BG: | VELUX Bulgaria EOOD 02/955 95 26 | NL: | VELUX Nederland B.V. 030 - 6 629 629 |
| BY: | VELUX Roof Windows FE (017) 217 7385 | NO: | VELUX Norge AS 22 51 06 00 |
| CA: | VELUX Canada Inc. 1 800 88-VELUX (888-3589) | NZ: | VELUX New Zealand Ltd. 0800 650 445 |
| CH: | VELUX Schweiz AG 0848 945 549 | PL: | VELUX Polska Sp. z o.o. (022) 33 77 000 / 33 77 070 |
| CL: | VELUX Chile Limitada 2 953 6789 | PT: | VELUX Portugal, Lda 21 880 00 60 |
| CN: | VELUX (CHINA) CO. LTD. 0316-607 27 27 | RO: | VELUX România S.R.L. 0-8008-83589 |
| CZ: | VELUX Česká republika, s.r.o. 531 015 511 | RS: | VELUX Srbija d.o.o. 011 3670 468 |
| DE: | VELUX Deutschland GmbH 0180-333 33 99 | RU: | ZAO VELUX (495) 737 75 20 |
| DK: | VELUX Danmark A/S 45 16 45 16 | SE: | VELUX Svenska AB 042/20 83 80 |
| EE: | VELUX Eesti OÜ 621 7790 | SI: | VELUX Slovenija d.o.o. 01 724 68 68 |
| ES: | VELUX Spain, S.A. 91 509 71 00 | SK: | VELUX Slovensko, s.r.o. (02) 33 000 555 |
| FI: | VELUX Suomi Oy 0207 290 800 | TR: | VELUX Çati Pencereleeri Ticaret Limited Şirketi 0 216 302 54 10 |
| FR: | VELUX France 0821 02 15 15 0,119€ TTC/min | UA: | VELUX Ukraina TOV (044) 2916070 |
| GB: | VELUX Company Ltd. 01592 778 225 | US: | VELUX America Inc. 1-800-88-VELUX |
| HR: | VELUX Hrvatska d.o.o. 01/5555 444 | | |
| HU: | VELUX Magyarország Kft. (06/1) 436-0601 | | |

www.velux.com